

Fig-2

RECEIVED
 JAN 31 2003
 TC 1700 MAIL ROOM




Fig-3D




Fig-3E

RECEIVED
JAN 28 1 2003
FBI MAIL ROOM




Fig-3F




Fig-3G





Fig-3H



Fig-3I



Fig-3J



RECEIVED
 JAN 31 2003
 TC 1700 MAIL ROOM




Fig-6

RECEIVED
 JAN 31 2003
 TC 1700 HALL ROOM




Fig-7




Fig-8

RECEIVED

JAN 31 2003

FC 1700 MAIL ROOM




Fig-9




Fig-10




Fig-11




Fig-12




Fig-1




Fig-3A





Fig-3B



SHOWS
 FABRIC
 RESTING ON 404
 NOT 407!

Fig-3C




Fig-2

23.28
12
11.28




Fig-3D




Fig-3E




Fig-3F




Fig-3G





Fig-3H






Fig-3I



Fig-3J










Fig-9




Fig-10




Fig-11




Fig-12